Treasury Department,

Bureau of the Mint,

Way 19, 1899

selbie, Esq.,

THO!

1220

Cashier American National Bank,

blisters or air-bubbles.

Deadwood, South Dakota.

pur letter of the 9th instant to the Chief of the Secret Ser-

a reply you are respectfully informed that it sometimes occurs at molling of strips from which blanks of the coin are out, blistyllow air-bubbles form and this destroys the sonority of a coin with

the from a blank cut from a strip of this character, while the coin while the coin makes. The flaw you speak of finding on the rim of the coin is

lereafter when any coins of this kind come within your observail will thank you to note the Mint mark and advise this Bureau,
if you will forward by registered mail any coin of this character
ill be redeemed.

Respectfully yours,

Director of the Mint.

Treasury Department, Bureau of the Mint, Washington, D.C.

May 19, 1899

William Selbie, Esq., Cashier American National Bank, Deadwood, South Dakota.

Sir:

Your letter of the 9th instant to the Chief of the Secret Service has been referred to this Bureau.

In reply you are respectfully informed that it sometimes occurs in the rolling of strips from which blanks of the coin are cut, blisters or air-bubbles form and this destroys the sonority of a coin struck from a blank out from a strip of this character, while the coin is genuine. The flaw you speak of finding on the rim of the coin is [also] due to blisters or air-bubbles.

Hereafter when any coins of this kind come within your observation, I will thank you to note the Mint mark and advise this Bureau, and if you will forward by registered mail any coin of this character it will be redeemed.

Respectfully yours,
[Signature] George E. Roberts
Director of the Mint.